



Question: Need some help or formula.

I measure two slot L1 & L2 which ever is smaller, I have to use as bonus tolerance. PCM on formula ok.

If $L1 > L2$ use $L2$ as bonus, if not then $L1$.

Thanks.