J&H Machine Tools



LUNCHEON LEARN

ZEISS

Checking distance

with regard to Rule #1

J&H Machine Tools

LUNCHEON LEARN

ZEISS

The print…. A Simple Block. Measure the thickness.

10+/-1

J&H Machine Tools



LUNCHEON LEARN

ZEISS

How do YOU do it now?

- Align on the left, report the X of the right?
- Distance between left and right?

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools



LUNCHEON LEARN

ZEISS

To do this right, we need to understand

RULE #1

Sounds important, doesn't it????

J&H Machine Tools

LUNCHEON LEARN

ZEISS

Definition Time!

"Where on ecified, the
limits of siz cribe the
extent to whi rm, as well
size, are allowec feature at each
cross section shall t m of an individual
feature is controlled b lowing three factors:
A) The surface or surface: f perfect form at MMC.
B) Where the actual local si f form is allowed equal to
the amount of such departu
C) There is no requirement fc AC limit of size is permitted to
vary from the true for to the ma

J&H Machine Tools



LUNCHEON LEARN

ZEISS

HEY!!!

WAKE UP!

J&H Machine Tools



LUNCHEON LEARN

ZEISS

What does it mean?

J&H Machine Tools



LUNCHEON LEARN

ZEISS

For checking distance between two parallel opposing planes, two things must happen in order for the part to be good:

- The part must be able to pass between two parallel planes at the maximum allowable distance apart.
- The “actual local size” of any cross-section on the part must be larger than the minimum allowable distance apart.

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools



LUNCHEON LEARN

ZEISS

Unfortunately, there is no "EASY BUTTON" way to report distance between planes correctly to "Rule #1".

"Rule #1" establishes a functional "go-no go" method of evaluating distance, not a solid numeric result, which CMMs are good at generating.

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Let's evaluate a few methods of checking distance and rate them on a scale of 1 to 5 for ease of use (practicality) and "correctness" considering "Rule #1".

5 is easiest and most "correct"

1 is hardest and least "correct"

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 1:

Checking the “X” value.

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS

J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 1:

Checking the “X” value.

Ease/Practicality: 5

“Correctness”: 1

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 2:

Cartesian Distance

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



10

THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



12

THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



10

THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

Method 2:

Cartesian Distance

Ease/Practicality: 4

"Correctness": 2

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 3:

Report Cartesian Distance and Parallelism

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Remember…

Parallelism = Distance between two planes, parallel to the datum, that contain all points of the evaluated plane.

J&H Machine Tools

LUNCHEON LEARN

ZEISS

J&H Machine Tools

LUNCHEON LEARN

ZEISS



10.5

THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



10.8

THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

Method 3:

Report Cartesian Distance and Parallelism

Ease/Practicality: 3

"Correctness": 3

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 4:

Cartesian Distance and TWO Parallelisms

J&H Machine Tools

LUNCHEON LEARN

ZEISS

J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



11

THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS

THIS PART IS BAD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS BAD!

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 4:

Cartesian Distance and TWO Parallelisms

Ease/Practicality: 2

"Correctness": 4

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 5:

Following the Standard

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Remember how to check distance, following Rule #1:

- The part must be able to pass between two parallel planes at the maximum allowable distance apart.
- The “actual local size” of any cross-section on the part must be larger than the minimum allowable distance apart.

J&H Machine Tools



LUNCHEON LEARN

ZEISS

First Part:

The part must be able to pass between two parallel planes at the maximum allowable distance apart.

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



Since there's no Datum, Gotta check both!



J&H Machine Tools



LUNCHEON LEARN

ZEISS

Second Part:

The “actual local size” of any cross-section on the part must be larger than the minimum allowable distance apart.

J&H Machine Tools

LUNCHEON LEARN

ZEISS

Measure the two planes with identical opposing measurement strategies.



J&H Machine Tools



LUNCHEON LEARN

ZEISS

Now, we need to

individually test the distance between all the points of a plane to the opposing point on the other plane. Report the smallest case.

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



OK, OK, OK, OK

To close out of point

Repeat the same procedure to create a new point for the opposing plane.

- New point
- Comment - Formula - LOOP1
- Recall Feature Points - PLANE
- Add Limits - Formula - LOOP1

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



One of these two MUST be good

This MUST be good

J&H Machine Tools

LUNCHEON LEARN



ZEISS

That's it.

Easy, huh?

It's really not all that bad.

J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools

LUNCHEON LEARN

ZEISS



J&H Machine Tools



LUNCHEON LEARN

ZEISS

J&H Machine Tools

LUNCHEON LEARN

ZEISS



THIS PART IS GOOD!

J&H Machine Tools

LUNCHEON LEARN

ZEISS

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Method 5:

Following the Standard

Ease/Practicality: 1

"Correctness": 4.9

J&H Machine Tools

LUNCHEON LEARN

J&H Machine Tools



LUNCHEON LEARN

ZEISS

Checking distance

with regard to Rule #1

Questions?