Dimensioning



Section A-A



Planar alignment



Actual dimensions





Coordinate system AB ready

Rotation 20.0000°
around X axis
and then:
evaluation of True Position