0.800
A-B


Always centered to the workpiece
Point of support
Workpiece
V-block (2x)
Dial indicator
Variable in vertical direction
Rotation of workpiece 0°-360°


0.800
A-B
C
Inhouse Standard
Variable in vertical direction simultaneous to dial indicator
Point of support
Workpiece
V-block (2x)
Dial indicator
Variable in vertical direction simultaneous to point of support
Rotation of workpiece 0°-360°