



* Question: Need some pcm help or formula.
 I measure two slot L1 & L2
 which ever is smaller, I have to use as
 bonus tolerance. pcm or formula ok.
 If $L1 > L2$ use L2 as Bonus, if not then L1.

Thanks.