

Properties

General Evaluation Filter/Outlier Strategy CAD

Strategies for new features. These settings are system settings and effective for all measurement plans.

only) Export of the characteristic attribute table in DiWeb Monitor.

Settings

Name: Current settings

Save Delete

Default settings

- Enabled
- Enabled
- Enabled
- Enabled
- Enabled
- Enabled
- Enabled

Strategy

Default Setting for Plane

Clearance Data

Polyline

OK Reset

Polyline

Default Setting for Plane

Speed 5.0000

Step Width .1

Number of points 1

Single points

Basic options Special Settings

Base Alignment

Edge distance 3.0000

Edge deviation 5.0000

OK Reset

Characteristic attribute

These elements  
Selection mode



In each mode, the CAD element via drag & drop