

CONTURA

Change angle for probing


A1 Z|-X

-8.4623

A2 Y|-X

39.2189

2nd letter (-X) identifies 0° angle and 1st letter (Z) identifies direction of positive angle rotation.



Reference Sphere
View from -Y

CONTURA

Change angle for probing


A1 Z|-X

-8.4623

A2 Y|-X

39.2189

2nd letter (-X) identifies 0° angle and 1st letter (Y) identifies direction of positive angle rotation.



Reference Sphere
View from +Z