How do I make a profile of a surface without using Freeform? - By Andrea Kerschl and Jim York

RULE: If you plan on using this method because your Calypso does not support Freeform or Curve. This method will ONLY work if you have a full reference frame for your profile. (ie A B and C) This will not work otherwise.



First using space points, plot your points on your curved surface.

📻 Calypso User Desk	- (C) Carl Zeiss - Perfe	t Basic manual profile	tutorial			
<u>File Edit View</u>	Resources Featu	es <u>C</u> onstruction	Size Form and Lo	cation <u>P</u> lan CA <u>C</u>	<u>)</u> E <u>x</u> tras Planne	r Window <u>?</u>
	* 0 0 ¢ 4		· · · · ·		1 😂 🐕 🧶 🛙	#1 Down
Basic Status: S	Select function o	r probe for sur	face measureme	nt with single p	points	
CMM Meas	urem Charact	ri Features				4
🛛 😐 Р	oint17		~ _		37/	
• Р	oint18			ېرل ەر ە 🗸	Ra Brig 20	
• P	oint19			> point11 > point10 > point9Po Point	Point/8 pinff/0/1/22	/) ⁽
• Р	oint20					
• Р	oint21					
• P	oint22			-		
• Р	oint23					~
🔹 🗢 Р	oint24					1
	alla i					

Now you need to put distances on each space point. To do this open up each point and check off "pt dist"

E, Calypso User Desk - (C) Carl Zeiss - Perfect Basic manual profile tutorial												
File Edit View Resources Feature Rememb	er the Locat											
		3 🕄 🕄	🧺 🎊 🧦 🛙 🖞	Down	Down 🗸							
Define Nominal Geometry (Prot Paintbrus	n!											
Measurem Emily Features X												
	😑 Poi											
1 4 3	Comment Projection Strategy											
Back Plane		None	Evaluation									
	Clearance Group	Nominal Definition	Alignment		Tolerance Classes							
Angle Probe	CP +Z 🚽	Options 🗸	(Base Alignmer 🗸		Fine	<u> </u>						
U	Tolerance For:	Nominal -1 9987	Actual	ISO 286-	Upper Tolerance Lower Toleran	ice Identifier						
Point1		0.6799	0.6803									
		-2 0910	-2 0910									
Point2	i .	-0.9761	-0.9761									
		-0.2172	-0.2172									
Point3	, k	0.0000	0.0000									
	PtDist		-0.0017		0 0020 🔽 -0 0020 [Snace Point Dist:						
Point4												
	Probin	g Direction	×									
Point5	Me	asure Normal Vecto	or Now									
		-		 								
Point6	Sigma	Form	Points									
	Min	Point no Point no	Max									
Point/												
Daint												
OK Recet												

Yes you must do this for each point. Remember the Paintbrush command can do this for you for each point.



Now your screen should look something like this.

Now we need to find the max point and min points for calculation. To do this, select "Size" "More" "Minimum feature" and "Maximum feature"



Open up Maximum Result first and select the "Features" tab, then highlight all your points and click okay. Do the same for your minimum result. You'll notice that the minimum has a negative value. We will take an extra step after we make those.

Calypso User Desk - (C) Carl Zeiss - Perfect Basic manual profile tut	orial							
File Edit View Resources Features Construction Si	ze F <u>o</u> rm and Location <u>P</u> lan CA <u>D</u> Extras Planner Window							
	Maximum Maximum1 Comment							
CMM Measurem Characteri Features	Fine V							
	Nominal 0.0000							
Space Point Distance_Point19								
space Point Distance_Point20								
Space Point Distance_Point21	Features							
Space Point Distance_Point22								
Space Point Distance_Point23								
Space Point Distance_Point24								
$\overset{X_{Max}}{\longleftrightarrow} Maximum1$								
X _{Min} Minimum1								
	Actual							
×	OK Reset							
Calypso User Desk - (C) Carl Zeiss - Perfect Basic manual profile	tutorial Size Form and Location Plan CAD Extras Planner W							
	× 8 0 1 1 4 0 4 × 5 #							
Select Feature	🖾 Maximum							
	X _{Max} Maximum1 Comment							
CMM Measurem Characteri Features	Fine V							
	Nominal 0.0000							
Space Point Distance_Point19	ISO286							
	Upper l'olerance 0.0020 None							
Space Point Distance_Point20								
Space Point Distance_Point21	Features Space Point Distance_Point1							
Space Point Distance_Point22	Space Point Distance_Point2 Space Point Distance_Point3 Space Point Distance_Point4							
Space Point Distance_Point23	Space Point Distance_Point5 Space Point Distance_Point6 Space Point Distance_Point7							
Space Point Distance_Point24	Space Point Distance_Point8 Space Point Distance_Point9 Space Point Distance_Point10							
$\overset{X_{Max}}{\longleftrightarrow} {}^{Maximum1}$	Space Point Distance_Point11 Space Point Distance_Point12 Space Point Distance_Point13							
	Space Point Distance_Point4							
	Actual -0.0001							
	OK Beast							

X _{Min}	Minimum1	Co	omment								
\leftrightarrow	Fine 🔽										
	Nominal	0.0000									
	ISO286										
	Upper Tolerance	0.0020 🗖 N	lone								
	Lower Tolerance	-0.0020	lone								
	Select Features										
Features	Space Point Distan Space Point Distan										
	Space Point Distance_Point12 Space Point Distance_Point13										
Snace Pr	nint Distance Point9										

Now we need to turn this into a positive value. To do that we can use a result element to get the absolute.



C. Result Element	
Result Element1 Comment	
Fine	
Nominal 0.0000	
IS0286	
Lower Interance None	
Dimension	
Calculate Formula Formula Dickt Click hore	
O Result Input	
Dialog Text formula	
Actual	
Select Feature	
Result Element	
Besult Element1 Comment	
Fine Take out spaces 3	
Nominal 0.0000 and add abc	×)
Formula	X
Length in Inch	
abs(getActual("Minimum1").actual)	
Function Loop Nominal Actual	Compute
Characteristics Eastures Attributes	
	click 2
Space Point Distance Point 7 Point 1 Space Point Distance Point 18 Point 2 Point 2 Point 2	see
Space Point Distance_Point19 Point3	
Space Point Distance_Point20 Point4 Point4	
Space Point Distance_Point22 Point6	
Space Point Dist 1 int24 Point8	
Maximum1 Point9 Minimum1 Point10	
Result Element1	
Maint12	M
	Help
OK	
OK Cancel	
Actual OK Cancel	

Calypso User Desk - (C) Carl Zelss - Perfect Basic manual profile	TUTORIAI
<u>File Edit View Resources Features Construction</u>	<u>Size Form and Location Plan CAD</u> Extras Planner Window ?
	🚿 🔆 🎝 🗊 🗐 😫 🕜 🎽 🥻 🧦 #1 Down 🔍
Basic Status: Select function or probe for sur	face measurement with single points
CMM Measurem Characteri Features	_
/ 1 1	
Space Point Distance_Point20	
Space Point Distance_Point21	
Space Point Distance_Point22	
Space Point Distance_Point23	
Space Point Distance_Point24	
$\overset{X_{\text{Max}}}{\longleftrightarrow} \text{Maximum1}$	
$\overset{\mathbf{X}_{\text{Min}}}{\longleftrightarrow} \overset{\text{Minimum1}}{\longleftrightarrow}$	
Result Element1	

Now you're going back to "Size" "More" "Maximum Result" and make another one.



Now finally do a final Result element containing your second Maximum Result and multiply it by two. Now you have the formula for your profile with space points. In this result element you can add your profile and tolerances.

<u>F</u> ile <u>E</u> dit	<u>View</u> <u>R</u> esources	Fe <u>a</u> tures	Construction	Size
5		8 4	M 88 89	Ŵ
Select Fe	eature			
2		<u>ৰূ</u> ত্ৰ	A D	
C. Result Ele	ement	heraderi .	<u> </u>	J
200	Result Element2		Comment	
0	Fine		-	
	Nominal	0.0000]	
	ISO286	1]	
	Upper Tolerance	0.0020	🔲 None	
	Lower Tolerance	-0.0020	None None	
−Dimensi	ion			
۲	Length 💦 🔿 Ang	le 🔘 I	Number	
Color	ulata Formula			
Eor	rmula			
🔿 Resu	ilt Input			
Dia	alog Text			
<			N	
Actual				

드 Ca	lypso l	Jser De:	sk - ((C) Ca	rl Zeis	s - Pe	rfect B	asic m	anual	profile	tutori	al								
<u>F</u> ile	<u>E</u> dit	View	Re	soui	rces	Fea	tures	<u>C</u> or	struc	tion	<u>S</u> ize	F <u>o</u> r	m and	l Loc	ation	<u>P</u> lan	CAD	Extra	s Planı	ner V
5	â		P	J	1	I	<i>(</i>)	80		09	2 2	X		Ū	E		2	2	A 5	#1
Sele	ct Fe	ature	,																	
	B		I.		Г	(ē	Ø		0¢)										
🚍 Re	sult Ele	ement		.		in such	and the state			23										
2	1	Res	ult E	lem	ent2				Comr	nent						~	_		\sim	~
		Fine									ă.								Z	
		Nomi	inal		ſ	1	0.007	0		ALC .										
		IS02	86		E F														Y	1
		llone	 • To	lora			0 002								1					
			- TU				0.002		NUI	e								$\langle \ \rangle$		
		Lowe	rio	lera	nce		0.002		Non	е					-					
Di	mens	ion — Longth		0	And		0	Nue	har										15	
	۲	Lengu		0	Any		C	NUN	iver											
۲	Calc	ulate F	orm	ula											$\overline{}$			\sim		
	Fo	rmula	10%	ovin			stual*	,							-			\bigcirc)/	
19912	y.	CACIUZ	il M	axiii	Tuniz	. j.a.		25					-							
0	Resi	ilt Inpu alog Te	it i∨t													_		\smile		
		nog re								~										
																				\square
										4		2		-					1	
	<								>				ľ ×			-				
		0.00	70		73													5		/
Actu	al	0.00	76																	