



Message when attempt with Master Probe manually inserted before Initialize.

```
11/18/19 12:01:07 pm
                              Accura Vast XT: Initializing
11/18/19 12:02:03 pm
                              Accura_Vast_XT: 28 Nominal position not in measurement range - commands cancelled - risk of collision
                              CNC Disabled, Re-Initialize Control
11/18/19 12:02:05 pm
11/18/19 12:02:05 pm
                              Accura_Vast_XT: 28 Nominal position not in measurement range - commands cancelled - risk of collision
                              Accura_Vast_XT: 6 Command rejected, cancel (D99...) recognized
11/18/19 12:02:06 pm
 11/18/19 12:02:18 pm
                              Accura Vast XT: CAA Correction active
11/18/19 12:02:18 pm
                             Accura_Vast_XT: Temperature sensor with name for part active and in auto mode
11/18/19 12:02:18 pm
11/18/19 12:02:18 pm
                             Accura_Vast_XT: Temperature correction for the X axis will be processed internally Accura_Vast_XT: Temperature correction for the Y axis will be processed internally
11/18/19 12:02:18 pm
                             Accura_Vast_XT: Temperature correction for the Z axis will be processed internally
11/18/19 12:02:18 pm Accura_Vast_XT: Temperature stylus not available or inactive
11/18/19 12:02:18 pm Accura_Vast_XT: Temperature sensor for table does not exist or is ignored
11/18/19 12:02:18 pm Accura_Vast_XT: CMM Ready
```



