






Z-Coordinate of a plane Least Squares plane Least Squares plane probing points unflat surface














Z-Coordinate of a plane 24 16 Plane parallel to X-Axis of alignment 8 Plane parallel to X-Axis of alignment Plane parallel to X-Axis of alignment X-Axis of alignment

