



The input of an "out of material" projection zone (P) means a press-fit-situation like shown below. Appending (M) at the perpendicularity callout is absolutely counterproductive!

