



⊕	∅0,80 (M) A B C
	∅0,25 (M) A

6x  
The lower tier describes the **making function** of the pattern. (6x)  
M&C makes sense.

2x  
The upper tier describes the **location and orientation** of the pattern. (6x)  
M&C definitely makes no sense because there isn't any making function.




6x pattern



6x

The lower tier describes the **mating function** of the pattern. (6x)  
MMC makes sense.



2x

The upper tier describes the **location and orientation** of the pattern. (6x)  
MMC definitely makes no sense because there isn't any mating function.

⊕	∅0,80 (M) A B C
	∅0,25 (M) A

Ref. 3;6

2x

The upper tier describes the **location and orientation** of the pattern. (6x)  
 MMC definitely makes no sense because there isn't any mating function.

6x

The lower tier describes the **mating function** of the pattern. (6x)  
 MMC makes sense.

