















True Position M AB M




Actual Material Boundary:
Tangential cylinder
constrained to datum A



datum C (MMB)
The center of datum C
has to be located within
the dashed zone



"center point" of the gage
always has to be located
within the tolerance zone



This is a circular
tolerance zone

