## Straightness of an axis ASME Y14.5 - 2018 create sections, you take the one (1) centroid of each section and use those to create an Gauss 🔭 Centroid Ø0.04 0.013 0.013 actual size: 0.013 The two-step-process: The one-step-process: 1.) Calculation of the Calculation of the center median points. point of a circle by Gauss-2.) Calculation of the algoritm. Thirteen cross centroid. sections perpendicular to UAME 0.0132 0.0134 Result: Result: So, what is the benefit when using the two-step-process?

13