


Pic 7-40

Dimensioning - as much as possible

FIG. 7-40(a)

PLTZF related to six bores

\oplus	$\varnothing 1$	\textcircled{M}	A	\textcircled{B}	\textcircled{M}



7.5.1.4


Pic 7-40

Dimensioning - as much as necessary

FIG. 7-40(a)

PLTZF related to two bores

\oplus	$\varnothing 1$	\textcircled{M}	A	\textcircled{B}	\textcircled{M}	2x



7.5.1.4