






Clean Contact Points



Use Flitz Polish





Apply and scrub with cu tip for a min
or so

Clean off with a rag
Do not let it dry

